

RECEIVED

JAN 11 1993

DIVISION OF
OIL GAS & MINING

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/92 To (mo./yr.) 1/93
2. DOGM File Number: M/041/008
3. Mine Name: Jensen Quarry
4. Mineral(s) Mined: Gypsum
5. Legal Description (Location of Lands Affected):
1/4, 1/4, Section 22, Township 22 S, Range 1 W
1/4, 1/4, Section 32, Township 22 S, Range 1 W
1/4, 1/4, Section 15, Township 22 S, Range 1 W
6. Name of Operator or Company: UNITED STATES GYPSUM COMPANY
7. Permanent Address: Corporate: 125 S. Franklin, Chicago, IL 60606-4678
Plant: P.O. Box 570160, Sigurd, UT. 84657

8. Company Representative (or designated operator):

Name: Chuck A. Whittington
Title: Quarry/Mill Manager
Address: P.O. Box 570160 Sigurd, UT. 84657
Phone: (801) 896-4484

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 122,478 Tons

3. How much new or additional acreage was affected during past year? 2.97

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

There was 61,954 cu. yds. of shale stripped with a dozer to expose
gypsum beds in 11 pits. A new section of haul road was added to
access the Three Sisters and 2C-2A No. 1 pits.

5. How much acreage was reclaimed during past year? 5.18

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

The 2.68 acre area of the 5B quarry and the 2.5 acre area of the C7
quarry were graded with a dozer to the natural contour of the
surrounding land. They will be seeded in the fall of 1993.

7. What is the total disturbed acreage at years end? 114.21
8. Briefly summarize mining and reclamation planned for the upcoming year.
There will be approximately 40,000 cu. yd. stripped resulting in less than 3.00 acres disturbed. Boulders will be salvaged at the 3-1B and crescent pits. The C2, 3-1B, crescent, 4A-NW pits and part of Lou's will be graded and seeded in 1993 for a total acreage of 7.65.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Chuck A. Whittington

Title of Operator: Quarry/Mill Manager

Signature of Operator: *Chuck A. Whittington*

Date: 1/7/93

jb
MR-AR